



PERSWEAR

Application and Specifications

Application

Surface should be absolutely clean and dry. Product may not work on insufficient cleaned surfaces. Ventilate the application area well. Spray on one square meter around 200 times with a standard PerWear bottle until surface becomes slightly wet. Surfaces which do not

absorb product should be spread with a cloth slightly. Wait for 24h for drying and curing period. Effect of product can change with respect to fabric type. Make a spot test on hidden part of your clothes.

Specifications

Packaging	150 mL
Appearance	Colorless liquid
Durability	Up to 1 years
Chemical Resistance	11>pH>1
Dry Film Thickness	90-100 nm
Density @23°C	1.01 g/cm ³
pH Value	4-5
Dry to Touch Time	6h
Application Temperature	+5°C to +45°C (≤50%RH)
Temperature Durability	150°C